


Technical Service Bulletin

10/28/2014

The purpose of this bulletin is to share information our quality team has discovered during the evaluation process of product returned to Hayward as warranty failures.

- During these evaluations a number of 12 volt UCL lights were found to have been connected to high voltage (120 volts)
- When a UCL light is damaged in this way it will show a scorch mark on the lens (front) as shown in the illustration below.



Connecting the light to line voltage burns out the light, and is not considered a warranty issue.

Warranty claims on lights determined to have failed due to high voltage will be considered on a case by case basis, but may be denied.

Please be certain when installing UCL lights, that they are installed with correct (12-14 volts) low voltage.